State of North Callina
Department of Environment,
Health and Natural Resources
Winston-Salem Regional Office

James B. Hunt, Jr., Governor Jonathan B. Howes, Secretary Leesha Fuller, Regional Manager



January 28, 1994

Daniel Shine Sun Company, Inc. 4041 Market Street Aston, PA 19014

SUBJECT:

Comprehensive Site Assessment: Summit Avenue Sunoco, Greensboro, Guilford

County, Groundwater Incident Number 10141

Dear Mr. Shine:

This office has received and reviewed <u>Comprehensive Site Assessment</u>; January 24, 1994, Groundwater Technology, for the subject location. This report does not meet the Comprehensive Site Assessment (CSA) requirements of completeness and therefore has been rejected. Specifically, this report does not delineate the extent of soil and groundwater contamination. Please refer to <u>Groundwater Section Guidelines For The Investigation and Remediation of Soils and Groundwater</u>, March 1993.

Until such a time that the above issues can be resolved, acceptance by the Division of the comprehensive site assessment report is refused. You must resubmit a complete CSA within thirty days from receipt of this notice or immediately contact Waddell Watters of this office to set up a schedule to meet the State's reporting requirements.

Responsibilities of owners of leaking underground storage tank systems are defined in 15A NCAC 2N. The consequences for failure to abide by regulatory responsibilities will be a request for the State to initiate enforcement actions.

If you have any questions, please contact Waddell Watters or me at the letterhead address or telephone number.

Sincerely,

Sherri V. Knight

Shem V. Knight

Hydrogeological Supervisor

cc: WSRO